CCR No. 97- 0640	**Logged Date** 4/22/97	**Rev.** -	**Request Type** CCR

Priority Routine [X] Urgent [ ] Emergency [ ]	**Affected Release** B	**Change Class** II

Title (description)
Update Release B.0 GSFC DAAC HW Baseline (Revision1)

Documents Affected None	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference** None

RTM Change [ ]   **Start New Baseline** [ ]

Problem
Update the GSFC DAAC HW baseline diagram to reflect new platform additions and fuctional re-assignments.

Proposed Solution
Review and approve attached file containing the HP->SUN and SGI ->SUN design changes.
1. GSFC DAAC B.0 HW baseline diagram.

Impact Analysis:

Organizations Affected:

BOO [ ]	Contracts [ ]	ECS Chief Eng [ ]	FOS [ ]	M&O [ ]
Procurement [ ]	QO [ ]	Rel. Dev [X]	Rel. A [ ]	Rel. C [ ]	SCDO Arch. [ ]
Science Off [ ]	Security [ ]	Subcontrct [ ]	Sys. Eng [ ]	Sys Verf Acpt [ ]

Cost: None [X]   Small [ ]   Medium [ ]   Large [ ]
(Not exceeding $100,000)($100,000 to $500,000)   (Over $500,000)

Schedule: None [ ]   Other

Additional LOC _____   Man-Months _____

Materials

Originator C. Van Steenberg, Const. Ofc. _____   Charleen Van Steenberg _____
Signature

Office Const. Mgr.   Office Manager Chip Schwartz _____
Signature   Date

Disposition   Approved [X]   Approved w/Comment [ ]   Forward [ ]   Disapproved [ ]

CCB Chairperson   Ramsey Billups _____
Signature   Date